

REPAIR COSTS

Part ID	DESCRIPTION	UNIT PRICE \$
ADDING TO EXISTING GARMENTS		
REPAIR - ADD EMBR LOGO GTX	REPAIR - Add Embroidery Logo Gore-Tex	85
REPAIR - ADD EMBR LOGO NYLON	REPAIR - Add Embroidery Logo Nylon	45
REPAIR - ADD EMBR NAME GTX	REPAIR - Add Embroidery Name Gore-Tex	75
REPAIR - ADD EMBROIDERY NAME	REPAIR - Add Embroidery Name	35
REPAIR - ADD PRINT LOGO	REPAIR - Add Screenprint Logo	50
REPAIR - ADD PRINT LOGO GTX	REPAIR - Add Screenprint Logo Gore-Tex	100
REPAIR - ADD TWILL	REPAIR - Add Twill	30
CHANGES TO EXISTING GARMENTS - (REQUIRES NEW PANEL)		
REPAIR - CHANGE EMBR GTX	REPAIR - Change Embroidered Logo Gtx	155
REPAIR - CHANGE EMBR NYLON	REPAIR - Change Embroidered Logo Nylon	95
REPAIR - CHANGE NAME GTX	REPAIR - Change Name Gore-Tex	145
REPAIR - CHANGE NAME NYLON	REPAIR - Change Name Nylon	85
REPAIR - CHANGE PRINT LOGO	REPAIR - Change Screenprint Logo	100
REPAIR - CHANGE PRINT LOGO GTX	REPAIR - Change Screenprint Logo GoreTex	150
REPAIR - CHG TWILL	REPAIR - Change Twill	50
REPLACEMENTS		
REPAIR - REPLACE BROKEN ZIPPER	REPAIR - Replace Broken Zipper	50
REPAIR - REPLACE PANEL GTX	REPAIR - Replace Panel Gore-Tex	70
REPAIR - REPLACE PANEL NYLON	REPAIR - Replace Panel Nylon	50

GARMENT'S DELIVERY DATE MUST FALL WITHIN PAST 3 MONTHS

****ABOVE COSTS PERTAIN TO CUSTOMER FAULT**

****IF BOATHOUSE FAULT, DISCOUNT COST TO \$0**